## REPORT

## TRUESDAIL LABORATORIES, INC.

CHEMISTS - MICROBIOLOGISTS - ENGINEERS

RESEARCH

DEVELOPMENT

TESTING

14201 FRANKLIN AVENUE TUSTIN, CALIF. 92680 AREA CODE 714 • 730-6239

AREA CODE 213 • 225-1564 FAX 714 • 730-6462

February 21, 1990

DATE

RECEIVED

January 31, 1990

LABORATORY NO.

36000

Douglas Aircraft Company Internal Mail Code 211-46

3855 Lakewood Boulevard

Long Beach, California

Attention: Kathleen Faretta

**SAMPLE** 

**CLIENT** 

Storm Drain Inspection - First Quarter

P.O. No.: T & M 23465C

INVESTIGATION As requested by the CRWQCB for NPDES permit numbers CA0001406 and CA0001414

## RESULTS

A representative of Truesdail Laboratories, Inc., tested the storm drain discharge on February 15, 1990, at the Douglas Torrance facility and Long Beach facility (003). The discharge was tested for flow rate, pH, and temperature. A grab sample was returned to the laboratory and analyzed according to the American Public Health Association's "Standard Methods," 17th Edition. The results are as follows:

Sample I.D.	Date	Time	Flow-gpd	Temp, F	pH, units
Long Beach (003)	2/15/90	12:25	48,787	64	8.1
Torrance	2/15/90	11:00	253	52	7.2

## MILLIGRAMS PER LITER

	Long Beach	Torrance
BOD (405.1)	6	27
Settleable Solids, mls/liter (160.5)	<0.1	0.2
Total Suspdended Solids (160.2)	23	45
Oil and Grease (415.1)	1	3

Respectfully submitted, TRUESDAIL LABORATORIES, INC.

Luis Perez, Supervisor

This report applies only to the sample, or samples, investigated and in the sample of similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.